

Eureka

Evaluation of the **Eureka Airport** yielded the following PCI values.

Section	Critical PCI	Surveyed PCIs				Predicted PCIs	
		1988	1991	1994	1997	2002	2007
A-1	55			92	77	60	43
R-1	55			96	94	77	66
T-1	55			87	85	72	62
T-2	55			100	87	73	63

Pavement Condition Index (PCI) to **Pavement Condition Rating** conversion:

0 ≤ **Failed** ≤ 10 < **Very Poor** ≤ 25 < **Poor** ≤ 40 < **Fair** ≤ 55 < **Good** ≤ 70 < **Very Good** ≤ 85 < **Excellent** ≤ 100

"XX" in PCI columns indicates previous PCI values have been voided to account for new construction.

No entry in PCI columns indicates no inspection of the pavement section for the year.

PCI predictions are based on the assumption that current maintenance practices will continue with no major reconstruction.

Your pavements are uniformly in "very good" condition or above. A routine maintenance program should preserve all but your apron in "good" condition and above their critical PCI for at least ten years. Patching of alligator cracking could prolong apron life beyond this projection.